

Introduction

A modified A/C Condenser Fan Assembly and Shroud are available for reduced A/C condenser fan noise.

Affected Vehicles


- 1994 and 1995 Model Year 4Runners.

Part Number Information

PART NUMBER	PART NAME
88590-35020	A/C Condenser Fan Assembly with shroud for reduction of fan noise

Repair Procedure

- Follow 1994/1995 Air Conditioner Installation Manual Procedures for part replacement.



NOTICE:

Installation of the modified A/C condenser fan on vehicles used under severe conditions (i.e. heavy loading, towing or rough road use, etc.) is not recommended as the cooling capacity of the modified fan is slightly less than that of the original fan.

Warranty Information

OPCODE	DESCRIPTION	TIME	OPN	T1	T2
AC7002	R & R Blower Assembly with shroud	1.2	88590-89101	91	99